

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESE

Location ID: 334831

Date: 9/21/2023



Entrance to Location – Photo #06510



SE Corner of Location – Photo #06511

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESE

Location ID: 334831

Date: 9/21/2023



Wellheads – Photo #06512



Separators – Photo #06514

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESE

Location ID: 334831

Date: 9/21/2023



Tank Battery – Photo #06513