

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SUPERIOR MWX 1 Pad

Location ID: 322467



Photo # 43 From entrance to location



Photo # 44 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SUPERIOR MWX 1 Pad

Location ID: 322467



Photo # 45 Location



Photo # 46 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SUPERIOR MWX 1 Pad

Location ID: 322467



Photo # 47 Location



Photo # 48 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SUPERIOR MWX 1 Pad

Location ID: 322467



Photo # 54 Unmarked deadman



Photo # 55 Same unmarked deadman from a different angle

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SUPERIOR MWX 1 Pad

Location ID: 322467



Photo # 60 Debris



Photo # 61 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SUPERIOR MWX 1 Pad

Location ID: 322467



Photo # 64 Unused equipment



Photo # 65 Unused equipment