

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 72-34 Pad

Location ID: 323994



Photo # 9974 From entrance to location



Photo # 9975 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 72-34 Pad

Location ID: 323994



Photo # 9976 Location



Photo # 9977 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 72-34 Pad

Location ID: 323994



Photo # 9979 Open ended pipe on separator/wildlife hazard



Photo # 9980 Open ended pipe on separator/wildlife hazard

