

# Inspection Photos

9/19/2023

**Operator:** LARAMIE ENERGY LLC #10433

**Location ID:** 324100

**Inspection No:** 696205265

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 324100



September 19, 2023



September 19, 2023

**Photo 1:** Photos taken from the east end of the Working Pad Surface. Photos 1-2 provide an overview of the Location from southwest, west, northwest to northeast



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 324100



September 19, 2023



September 19, 2023

**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 324100



**Photo 3:** Photo taken from the Cascade Creek #697-09-10A well; well was PA 9/10/2021. Photo shows riser remaining.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 324100



**Photo 4:** Photo taken from the interim areas on the northeast end of the Location. Though vegetation appears to be progressing towards 1003 standards, site has not achieved a uniform establishment. Photos also shows examples of areas where topsoil had not been replaced.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 324100



**Photo 5:** Photo right taken from the eastern interim areas where topsoil had not been replaced. Photo right taken from the western interim areas where topsoil had been replaced. Vegetation within areas of the Location where topsoil has been replaced is achieving a more uniform establishment



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 324100



**Photo 6:** 2021 COGIS aerial image. Arrow shows areas of the Location where topsoil had been replaced.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources