

Inspection Photos
Location Name: Simpson Pad 15-219HN
Location ID: 440858



Energy & Carbon Management Commission
40.48719, -104.87324, 1442.4m, 216°
09/25/2023 12:16:28

Production facility



Energy & Carbon Management Commission
40.48831, -104.87406, 1453.6m, 113°
09/25/2023 12:17:48

Wellheads

Inspection Photos
Location Name: Simpson Pad 15-219HN
Location ID: 440858



Unused equipment



Unused equipment

