

Inspection Photos
Location Name: Brand #1
Location ID: 311305



Photo 1 Location



Photo 2 WH sign

Inspection Photos
Location Name: Brand #1
Location ID: 311305



Photo 3 WH.



Photo 4 Pump Jack.

Inspection Photos
Location Name: Brand #1
Location ID: 311305



Photo 5 Unused plastic drum.



Photo 6 Unused lube pump.

Inspection Photos
Location Name: Brand #1
Location ID: 311305



Photo 7 Unused propane tank.



Photo 8 Unused steel drum.

Inspection Photos
Location Name: Brand #1
Location ID: 311305



Photo 9 Unused flow line with ball valve not LOTO .




Photo 10 Unused flow line with ball valve not LOTO .

Inspection Photos
Location Name: Brand #1
Location ID: 311305



Photo 11 Stained soil around the WH and pump jack base.



Photo 12 Stained soil around the WH and pump jack base.

Inspection Photos
Location Name: Brand #1
Location ID: 311305



Photo 13 Stained soil under the pump jack engine skid plate.



Photo 14 Stained soil under the pump jack engine skid plate.

Inspection Photos
Location Name: Brand #1
Location ID: 311305



Colorado Energy & Carbon Management Commission
40.10702, -104.80279, 4806.2ft
09/25/2023 12:07:24

Photo 15 TB sign.



Colorado Energy & Carbon Management Commission
40.10705, -104.80271, 4816.9ft
09/25/2023 12:07:36

Photo 16 TB.



Inspection Photos
Location Name: Brand #1
Location ID: 311305



Photo 17 Marked flow line not LOTO.



Photo 18 Marked flow line not LOTO.

Inspection Photos
Location Name: Brand #1
Location ID: 311305



Photo 19 Marked flow line not LOTO.