

Inspection Photos

Loc: 307267

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 9/25/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the access road which has been repaired and stabilized..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:307267 | Date: 9/25/2023

Inspection Photos



Photo 2. The road side has been stabilized with large rock rip/rap.



Inspection Photos



Photo 3. Facing southwest toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:307267 | Date: 9/25/2023