

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FNB OF GRAND JUNCTION TR GV 87-36 Pad

Location ID: 334815



Photo # 541 From entrance to location



Photo # 542 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FNB OF GRAND JUNCTION TR GV 87-36 Pad

Location ID: 334815



Photo # 543 Location



Photo # 544 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FNB OF GRAND JUNCTION TR GV 87-36 Pad

Location ID: 334815



Photo # 545 Location



Photo # 546 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FNB OF GRAND JUNCTION TR GV 87-36 Pad

Location ID: 334815



Photo # 547 Improperly marked deadman



Photo # 548 Same improperly marked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FNB OF GRAND JUNCTION TR GV 87-36 Pad

Location ID: 334815



Photo # 549 Stained soils & gravel



Photo # 550 Stained soils & gravel