

Inspection Photos
Location Name: Shoe 1
API # 05-123-05061



Access road covered in overgrown vegetation



Well & overgrown vegetation

Inspection Photos
Location Name: Shoe 1
API # 05-123-05061



September 25, 2023 at 10:20 AM
+40 1186 -104.3266
8° N
Weld County
Energy & Carbon Management Commission

Wrong operator sign