

Inspection Photos

Inspection Date: 9/12/2023

Operator: Booco's Contract Services Inc 9006

Location ID: 316789

Location Name: Peltier #11-12

Inspection Document #: 696205272

Routt County, Colorado

SENW 11 6N87W

Logan Maxwell and Aaron Trujillo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Peltier #11-12
Location ID: 316789



Photo 1. Site overview taken from west of the Location facing northwest.



Photo 2. Site overview taken from west of the Location facing north.

Inspection Photos
Location Name: Peltier #11-12
Location ID: 316789



Photo 3. Site overview taken from west of the Location facing east.



Photo 4. Site overview taken from west of the Location facing southeast.

Inspection Photos
Location Name: Peltier #11-12
Location ID: 316789

Sep 12, 2023 at 9:31:13 AM
Steamboat Springs CO 80487
United States



Photo 5. Site overview taken from west of the Location facing southwest.

Sep 12, 2023 at 9:31:16 AM
Steamboat Springs CO 80487
United States



Photo 6. Site overview taken from west of the Location facing west.

Inspection Photos
Location Name: Peltier #11-12
Location ID: 316789



Photo 7. Noxious weeds established across Location (Houndstongue, List B).



Photo 8. Noxious weeds established across Location (Houndstongue, List B).

Inspection Photos
Location Name: Peltier #11-12
Location ID: 316789



Photo 9. Noxious weeds established across Location (Canada Thistle, List B).

Inspection Photos
Location Name: Peltier #11-12
Location ID: 316789




Photo 11.



Photo 12.




Photo 13.

Photos 11-13: Anchors observed across Location.



Inspection Photos
Location Name: Peltier #11-12
Location ID: 316789



Photo 14. Trash and debris (including weed) found across Location.



Photo 15. Trash and debris (including weed) found across Location.

Inspection Photos
Location Name: Peltier #11-12
Location ID: 316789



Photo 16. Gravel not removed and pad compaction has not been alleviated



Photo 17. Old Operator sign still remaining on Location; well was operated by Comet Ridge, before transferring to Pine Ridge in 2008, and then Booco's Contract Services in 2010.

Inspection Photos
Location Name: Peltier #11-12
Location ID: 316789



Photo 18. Observed gully erosion on fill slope.



Photo 19. Observed gully erosion on fill slope.

Inspection Photos
Location Name: Peltier #11-12
Location ID: 316789



Photo 20. Observed erosion occurring on cut slope.



Photo 21. Observed erosion occurring on cut slope.