

# Inspection Photos

Loc: 307351

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 9/25/2023

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing north at the beginning of the main road. Additional gravel has been applied to areas of the road.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:307351 | Date: 9/25/2023

## Inspection Photos



**Photo 2.** Facing northwest along the main road. Additional gravel has been applied to areas of the road.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:307351 | Date: 9/25/2023

## Inspection Photos



**Photo 3.** Facing southeast toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:307351 | Date: 9/25/2023