

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403285176

Receive Date:

09/20/2023

Report taken by:

RICK ALLISON

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>SCHNEIDER ENERGY SERVICES INC</u>	Operator No: <u>76840</u>	Phone Numbers
Address: <u>P O BOX 889</u>		Phone: <u>(970) 381-9588</u>
City: <u>FORT MORGAN</u>	State: <u>CO</u>	Zip: <u>80701</u>
Contact Person: <u>Jeff Schneider</u>	Email: <u>jeff@schneiderenergy.com</u>	Mobile: <u>()</u>

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 21910 Initial Form 27 Document #: 402948608

PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☐ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☐ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☒ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☐ Rule 915.b: Request to leave elevated inorganics in situ.
- ☐ Other: _____

SITE INFORMATION

No Multiple Facilities

Facility Type: <u>LOCATION</u>	Facility ID: <u>465923</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>Eaton Field 1</u>	Latitude: <u>40.539297</u>	Longitude: <u>-104.709378</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>SWSW</u>	Sec: <u>30</u>	Twp: <u>7N</u>	Range: <u>65W</u>
Meridian: <u>6</u>	Sensitive Area? <u>Yes</u>		

SITE CONDITIONS

General soil type - USCS Classifications SM Most Sensitive Adjacent Land Use Cropland

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? No

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

--

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- ☒ E&P Waste ☐ Other E&P Waste ☐ Non-E&P Waste
- ☒ Produced Water ☐ Workover Fluids
- ☒ Oil ☐ Tank Bottoms
- ☒ Condensate ☐ Pigging Waste
- ☐ Drilling Fluids ☐ Rig Wash
- ☐ Drill Cuttings ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
No	GROUNDWATER	Groundwater not encountered	inspection
No	SOILS	No hydrocarbon impacts encountered	inspection/soil samples/laboratory analytical results

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Decommissioning activities were completed at the Eaton Field #1 production facility on September 27, 2022. Groundwater was not encountered during excavation activities. Visual inspection and field screening of soils at one separator, one meter house, two produced water vessel (PWV), and four aboveground storage tanks (AST) were conducted following removal activities, and soil samples (SEP-B01@3", PW-B01@5', PW-W01@2.5', PW-B02@5', PW-E02@2.5', AST-B01@3", AST-B03@3", AST-B05@3", and AST-B07@3") were submitted for laboratory analysis to determine if a release occurred. Laboratory analytical results indicated that pH was elevated in soil at the former AST location (AST-B05@3"). A topographic Site Location Map showing the geographic setting of the site location is provided as Figure 1. Soil sample location and field screening data is presented in Table 1. The facility soil sample and field screening locations are illustrated on Figure 2. The associated FL to Wattenberg Drilling Fund (WDF) #3 and WDF #4 has been abandoned in place per Rule 1105.d. and associated Form 44 (Doc # 403329320) which has been previously submitted.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

- ☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

On September 27, 2022, soil samples were collected from the bases (PW-B01@5', PW-B02@5'), west sidewall (PW-W01@2.5'), and east sidewall (PW-E02@2.5') of the PWV excavations, the beneath the separator (SEP-B01@3"), and beneath the ASTs (AST-B01@3", AST-B03@3", AST-B05@3", AST-B07@3"). The soil samples were submitted for laboratory analysis of BTEX, naphthalene, 1,2,4-TMB, 1,3,5-TMB, TPH-GRO (C6-C10), TPH-DRO (C10-C28), TPH-ORO (C28-C40), PAHs, pH, EC, SAR, and boron using COGCC approved methods. Analytical results indicated that constituent concentrations in the soil samples were in compliance with COGCC Table 915-1 standards, with the exception of the pH value in AST-B05@3". The pH value was within the acceptable range of soil variability, and it alone does not indicate that a release occurred at the former AST location. As such, it was determined to be acceptable to leave in place. Soil analytical results are presented in Tables 2 through 4.

Proposed Groundwater Sampling

- ☐ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Groundwater was not encountered during decommissioning activities.

Proposed Surface Water Sampling

- ☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

- ☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

On September 27, 2022, visual inspections and field screening of soils was conducted at six sidewalls of the PWV excavations, one former meter house, and four former ASTs. Based on the inspection and screening results, hydrocarbon-impacted soils were not observed at the soil screening locations. As a result, no soil samples were submitted for laboratory analysis from these areas in accordance with the COGCC Operator Guidance for Oil & Gas Facility Closure document. Soil sample location and field screening data are presented in Table 1. Soil analytical results are summarized in Tables 2 through 4. The soil sample and field screening locations are illustrated on Figure 2. The laboratory analytical report is provided as Attachment A. The field notes and photographic log are provided as Attachment B.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 9

Number of soil samples exceeding 915-1 1

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 0

NA / ND

-- Highest concentration of TPH (mg/kg) 265.1

-- Highest concentration of SAR 2.67

BTEX > 915-1 No

Vertical Extent > 915-1 (in feet) 0

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet)

Number of groundwater monitoring wells installed

Number of groundwater samples exceeding 915-1

Highest concentration of Benzene (µg/l)

Highest concentration of Toluene (µg/l)

Highest concentration of Ethylbenzene (µg/l)

Highest concentration of Xylene (µg/l)

Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

Background soil samples PW-BG01@3' and PW-BG01@6' were collected from native material adjacent to the PWV excavations. The background soil samples were submitted for laboratory analysis of the Soil Suitability for Reclamation Parameters using standard methods appropriate for detecting the target analytes in Table 915-1. Analytical results for the background soil samples are presented in Table 4.

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☐ Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Laboratory results indicate that constituent concentrations in the soil samples collected from the bases, west, and east sidewalls of the PWV excavation (PW-B01@5', PW-B02@5', PW-W01@2.5', PW-E02@2.5'), separator excavations (SEP-B01@3'), and beneath the former ASTs (AST-B01@3", AST-B03@3", AST-B05@3", AST-B07@3") were in compliance with the COGCC Table 915-1 standards, with the exception to the pH value for AST-B05@3". However, the pH result was within the acceptable range of soil variability, and it alone does not indicate that a hydrocarbon or produced water release occurred at the former AST location. As such, it was determined to be acceptable to leave in place, and no soils were removed. The excavation areas will be backfilled and contoured to match preexisting site conditions.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Laboratory results indicate that constituent concentrations in the soil samples collected from the bases, west, and east sidewalls of the PWV excavation (PW-B01@5', PW-B02@5', PW-W01@2.5', PW-E02@2.5'), separator excavations (SEP-B01@3"), and beneath the former ASTs (AST-B01@3", AST-B03@3", AST-B05@3", AST-B07@3") were in compliance with the COGCC Table 915-1 standards, with the exception to the pH value for AST-B05@3". However, the pH result was within the acceptable range of soil variability, and it alone does not indicate that a hydrocarbon or produced water release occurred at the former AST location. Due to the depth of the elevated pH result, it was determined to be acceptable to leave in place, and no soils were removed. Groundwater was not encountered in the cut and cap excavation area or flowline removal potholes. Based on the analytical and soil screening data presented herein, assessment is complete at this site and no further activities are required. As such, Schneider Energy Service is requesting a No Further Action (NFA) determination for this location.

Soil Remediation Summary

☐ In Situ

_____ Bioremediation (or enhanced bioremediation)
 _____ Chemical oxidation
 _____ Air sparge / Soil vapor extraction
 _____ Natural Attenuation
 _____ Other _____

☐ Ex Situ

_____ Excavate and offsite disposal
 _____ If Yes: Estimated Volume (Cubic Yards) _____
 _____ Name of Licensed Disposal Facility or COGCC Facility ID # _____
 _____ Excavate and onsite remediation
 _____ Land Treatment
 _____ Bioremediation (or enhanced bioremediation)
 _____ Chemical oxidation
 _____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)
 _____ Chemical oxidation
 _____ Air sparge / Soil vapor extraction
 _____ Natural Attenuation
 _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

☐ Quarterly☐ Semi-Annually☐ Annually☒ Other

☐ Request Alternative Reporting Schedule:

☐ Semi-Annually☐ Annually☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type:

☐ Groundwater Monitoring☐ Land Treatment Progress Report☐ O&M Report☒ Other NFA Request

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Operator anticipates the remaining cost for this project to be: \$

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation?

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards

E&P waste (solid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project?

If YES:

☒ Compliant with Rule 913.h.(1).

☐ Compliant with Rule 913.h.(2).

☐ Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards?

Does the previous reply indicate consideration of background concentrations?

Does Groundwater meet Table 915-1 standards?

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the COGCC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with COGCC 1000 Series Rules

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim

☐ Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. _____

Proposed date of completion of Reclamation. _____

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, or date of discovery. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 09/27/2022

Proposed site investigation commencement. 09/27/2022

Proposed completion of site investigation. 09/27/2022

REMEDIAL ACTION DATES

Proposed start date of Remediation. _____

Proposed date of completion of Remediation. _____

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☐ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT

Laboratory results indicate that constituent concentrations in sample FL-B09@5' were in compliance with COGCC Table 915-1 standards, with exception to the pH value in AST-B05@3". However, the pH result was within the acceptable range of soil variability, and it alone does not indicate that a hydrocarbon or produced water release occurred at the former AST location. Due to the depth of the elevated pH result, it was determined to be acceptable to leave in place. As a result, Schneider Energy Services is requesting an NFA determination for this location, based on the analytical and soil screening data provided herein.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Jeff Schneider

Title: President

Submit Date: 09/20/2023

Email: jeff@schneiderenergy.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: RICK ALLISON

Date: 09/26/2023

Remediation Project Number: 21910

COA Type**Description**

	<p>Based on the information presented, it appears that no further remedial action is necessary at this time and the ECMC approves the closure request. However, should future conditions at the site indicate contaminant concentrations in soils exceeding ECMC standards or if groundwater is found to be impacted, then further investigation and/or remediation activities may be required.</p> <p>The surface area disturbed by the remediation activity shall be reclaimed in accordance with the 1000 Series Reclamation Rules. For locations with active ongoing oil and gas operations, comply with Rule 1003 interim reclamation requirements and for locations that will no longer have active oil and gas operations, comply with Rule 1004 Final Reclamation requirements.</p>
1 COA	

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

403285176	INVESTIGATION/REMEDATION WORKPLAN (SUPPLEMENTAL)
403285427	PHOTO DOCUMENTATION
403285428	SITE MAP
403285433	ANALYTICAL RESULTS
403285434	ANALYTICAL RESULTS
403285527	SOIL SAMPLE LOCATION MAP
403536333	OTHER
403542296	FORM 27-SUPPLEMENTAL-SUBMITTED

Total Attach: 8 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)