

Storm Water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MOORE 27-42-6S-94W Pad
Location ID: 323788



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas/Bald Eagle
Nest/Roost sites & in close proximity to NSO Habitat area.
Location is approximately 104 yards from the Colorado River
& 321 yards from Porcupine Creek.
Section/Township/Range: 27 6S94W**

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MOORE 27-42-6S-94W Pad
Location ID: 323788



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.



Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MOORE 27-42-6S-94W Pad
Location ID: 323788



Photo # 874 Erosion & transport of sediment



Photo # 875 Erosion & transport of sediment

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MOORE 27-42-6S-94W Pad
Location ID: 323788



Photo # 876 Erosion & transport of sediment



Photo # 877 Erosion & transport of sediment

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MOORE 27-42-6S-94W Pad
Location ID: 323788



Photo # 878 Erosion & transport of sediment



Photo # 879 Erosion & transport of sediment

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC MOORE 27-42-6S-94W Pad
Location ID: 323788



Photo # 880 Erosion & transport of sediment



Photo # 881 Erosion & transport of sediment