


North Shore Exploration and Production Inc
Smith 1
Location ID: 313052



Access road to location



Debris

North Shore Exploration and Production Inc
Smith 1
Location ID: 313052



Staining




Staining

North Shore Exploration and Production Inc
Smith 1
Location ID: 313052



Missing required information



Open end tank valve

North Shore Exploration and Production Inc
Smith 1
Location ID: 313052




Open to wildlife



Open end tank valve

North Shore Exploration and Production Inc
Smith 1
Location ID: 313052



Vent open to wildlife



Debris

North Shore Exploration and Production Inc
Smith 1
Location ID: 313052



Unused equipment



Debris

**North Shore Exploration and Production Inc
Smith 1
Location ID: 313052**



Debris



Staining under trash basket

North Shore Exploration and Production Inc
Smith 1
Location ID: 313052



Staining under trash basket



Debris

North Shore Exploration and Production Inc
Smith 1
Location ID: 313052



Chemical tote. No containment.



Debris

**North Shore Exploration and Production Inc
Smith 1
Location ID: 313052**



Missing required information



Open to wildlife. Debris inside containment

North Shore Exploration and Production Inc
Smith 1
Location ID: 313052



Debris



Debris

**North Shore Exploration and Production Inc
Smith 1
Location ID: 313052**



Open to wildlife



Venting. Same as 9/13/23.

North Shore Exploration and Production Inc
Smith 1
Location ID: 313052



Unused equipment



Debris

North Shore Exploration and Production Inc
Smith 1
Location ID: 313052



New ECD. Not in service. Debris.



Debris

**North Shore Exploration and Production Inc
Smith 1
Location ID: 313052**



Staining near combustor



Unused equipment open to wildlife

North Shore Exploration and Production Inc
Smith 1
Location ID: 313052



Open to wildlife




Debris

North Shore Exploration and Production Inc
Smith 1
Location ID: 313052



Debris



Skid covered in oily liquid

North Shore Exploration and Production Inc
Smith 1
Location ID: 313052



Debris inside containment




Debris

North Shore Exploration and Production Inc
Smith 1
Location ID: 313052




Staining from inside leaks



Debris

North Shore Exploration and Production Inc
Smith 1
Location ID: 313052



Open to wildlife



Unused equipment

North Shore Exploration and Production Inc
Smith 1
Location ID: 313052



Location view from Southwest corner. Entrance to location.



Location view from Northwest corner

**North Shore Exploration and Production Inc
Smith 1
Location ID: 313052**



Location view from Northeast corner. Staining.



Location view from Southeast corner