


Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 119-33 Pad
Location ID: 324059



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas**
Section/Township/Range: 33 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 119-33 Pad
Location ID: 324059



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 119-33 Pad
Location ID: 324059



Photo # 618 Erosion & transport of sediment off location (N/NE area of location)



Photo # 619 Erosion & transport of sediment off location (N/NE area of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 119-33 Pad
Location ID: 324059



Photo # 620 Erosion & transport of sediment off location (N/NE area of location)



Photo # 621 Erosion & transport of sediment off location (N/NE area of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 119-33 Pad
Location ID: 324059



Photo # 622 Erosion & transport of sediment off location (N/NE area of location)



Photo # 623 Culvert needs maintenance (near wellhead)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 119-33 Pad
Location ID: 324059



Photo # 624 Culvert needs maintenance (near wellhead)



Photo # 625 Culvert needs maintenance (near wellhead)