

Inspection Photos

Loc: 308264

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 9/25/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest at the beginning of the main road which remains per approved variance.



Inspection Photos



Photo 2. Facing southwest toward the location. Gravel remains along the portion of the access road entering into the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308264 | Date: 9/25/2023

Inspection Photos



Photo 3. Facing southeast toward the location fill slope which is stabilized with vegetation. The electric utility line remains to the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308264 | Date: 9/25/2023

Inspection Photos



Photo 4. Facing northeast toward the location which is stabilized with perennial vegetation..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308264 | Date: 9/25/2023

Inspection Photos



Photo 5. Facing north toward the location cut slope which is stabilized with perennial vegetation.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308264 | Date: 9/25/2023

Inspection Photos



Photo 6. Facing southwest toward the location cut slope which is stabilized with perennial vegetation.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:308264 | Date: 9/25/2023