

Inspection Photos
Location Name: DF Ranch 9-24
Location ID: 415207



Photo 1 – Pumping Unit

Photo 2 – Wellhead

Inspection Photos
Location Name: DF Ranch 9-24
Location ID: 415207



Photo 3 – Well Sign



Photo 4 – Engine and Housing Removed