

Inspection Photos
Location Name: DF Ranch 1161 9-32
Location ID: 414980



Photo 1 – Pumping Unit



Photo 2 – Wellhead

Inspection Photos
Location Name: DF Ranch 1161 9-32
Location ID: 414980



Photo 3 – Well Sign



Photo 4 – Fencing in disrepair

Inspection Photos
Location Name: DF Ranch 1161 9-32
Location ID: 414980



Photo 5 – Fencing in disrepair