

Inspection Photos
Location Name: Sliverback 36-A PAD
Location ID: 443555



Photo 1 – Gas Meters



Photo 2 – Production Equipment

Inspection Photos
Location Name: Sliverback 36-A PAD
Location ID: 443555



Photo 3 – Wildlife Netting missing from Day Tank Secondary Containments



Photo 4 – Flare

Inspection Photos
Location Name: Sliverback 36-A PAD
Location ID: 443555



Photo 5 – Pumping Units



Photo 6 – Gas Engines

Inspection Photos
Location Name: Sliverback 36-A PAD
Location ID: 443555



Photo 7 – Maintenance Tank



Photo 8 – Unused Chemical Tank and Stand West of Maint. Tank

Inspection Photos
Location Name: Sliverback 36-A PAD
Location ID: 443555



Photo 9 – Tank Battery



Photo 10 – Tank Battery Sign



Inspection Photos
Location Name: Sliverback 36-A PAD
Location ID: 443555



Photo 11 – ECDs



Photo 12 – Separators