

Operator: 8 North

Location Name: DF Ranch 3-41, 3-43

Loc ID: 461761

Inspection: 696305274



Exhibit A

CA: 100 BBLS vessel- Missing capacity label; see photos. Install signs to comply with Rule 605.h.

CA Resolution: Missing capacity label has been added to comply with rule 605.h.