

Inspection Photos

Location Name: LARAMIE ENERGY LLC, CC/0629-02 Pad

Location ID: 335149

Date: 9/26/2023



Entrance to Location – Photo #06619



Wellheads – Photo #06621

Inspection Photos

Location Name: LARAMIE ENERGY LLC, CC/0629-02 Pad

Location ID: 335149

Date: 9/26/2023



Separator – Photo #06624



Tank Battery – Photo #06623

