

Operator: 8 North

Location Name: DF RANCH-611N61W 3NESE

Loc ID: 302823

Inspection: 696305272



Exhibit A



Exhibit B



Exhibit C



Exhibit D

CA: Weeds at wellsite; see photos. Comply with rule 606.

CA Resolution: Weeds have been properly cleared to comply with rule 606.