

**Inspection Photos**  
**Location Name: Mosher 1-1H**  
**API: 05-073-06393**



Brian Welsh SE Field Inspector COGCC  
38.93747, -103.38843, 4803.9ft  
09/21/2023 09:21:58

**Location photo**



Brian Welsh SE Field Inspector COGCC  
38.93802, -103.38871, 4813.5ft  
09/21/2023 10:00:26

**Concrete blocks laying around**

Inspection Photos  
Location Name: Mosher 1-1H  
API: 05-073-06393



Electrical wires exposed



AGT 2 water tank load line

Inspection Photos  
Location Name: Mosher 1-1H  
API: 05-073-06393



AGT 2 water tank has leaking rust spots



AGT 1 water tank is rotted out and needs removed

Inspection Photos  
Location Name: Mosher 1-1H  
API: 05-073-06393



**AGT 4 water tank leak**



**This water transfer pipe has a hole and needs repaired**