

Storm Water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC HAYNES-HARRIS 27-43-6S-94W Pad

Location ID: 335258



Location Overview: Location is within High Priority/Density/NSO/Black Bear Habitat areas & Bald Eagle Nest/Roost sites. Location is approximately 142 yards from Porcupine Creek & approximately 311 yards from the Colorado River.

Section/Township/Range: 27 6S94W

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC HAYNES-HARRIS 27-43-6S-94W Pad
Location ID: 335258



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC HAYNES-HARRIS 27-43-6S-94W Pad

Location ID: 335258



Photo # 697 Erosion & transport of sediment



Photo # 698 Erosion & transport of sediment

Storm water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC HAYNES-HARRIS 27-43-6S-94W Pad

Location ID: 335258



Photo # 699 Erosion & transport of sediment



Photo # 700 Erosion & transport of sediment

Storm water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC HAYNES-HARRIS 27-43-6S-94W Pad

Location ID: 335258



Photo # 701 Erosion & transport of sediment



Photo # 702 Erosion & transport of sediment

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC HAYNES-HARRIS 27-43-6S-94W Pad
Location ID: 335258



Photo # 703 Erosion & transport of sediment



Photo # 704 Erosion & transport of sediment

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC HAYNES-HARRIS 27-43-6S-94W Pad
Location ID: 335258



Photo # 705 Erosion & transport of sediment



Photo # 706 Erosion & transport of sediment

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC HAYNES-HARRIS 27-43-6S-94W Pad
Location ID: 335258



Photo # 707 Erosion & transport of sediment



Photo # 708 Erosion & transport of sediment

Storm water Management and Erosion control

Location Name: MUSTANG RESOURCES LLC HAYNES-HARRIS 27-43-6S-94W Pad

Location ID: 335258



Photo # 709 Erosion & transport of sediment

