

Operator: 8 North

Location Name: DF Ranch 10-11, 13, 42, 44

Loc ID: 460765

Inspection: 696305269



Exhibit A

CA: North Tank Capacity labels faded and are no longer visible. Install signs to comply with rule 605.h.

CA Resolution: Capacity labels have been added to the north tank to comply with rule 605.h.