

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 1-42 (RN1) Pad

Location #: 323989



**Photo # 1146 From entrance to location**



**Photo # 1147 From entrance to location**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 1-42 (RN1) Pad

Location #: 323989



Photo # 1148 Location



Photo # 1149 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 1-42 (RN1) Pad

Location #: 323989



Photo # 1150 Location



Photo # 1151 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 1-42 (RN1) Pad

Location #: 323989



Sep 29, 2023 at 12:19:06 PM

Photo # 1152 Location



Sep 29, 2023 at 12:20:07 PM

Photo # 1153 Open ended pipe on production unit



## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 1-42 (RN1) Pad

Location #: 323989



Photo # 1154 Unmarked deadman



Photo # 1155 Same unmarked deadman from different angle