

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 1-31 (RL1) Pad

Location #: 323999



Photo # 1184 From entrance to location



Photo # 1185 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC SAVAGE 1-31 (RL1) Pad
Location #: 323999



Photo # 1186 Location



Photo # 1187 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 1-31 (RL1) Pad

Location #: 323999



Photo # 1188 Location



Photo # 1189 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 1-31 (RL1) Pad

Location #: 323999




Photo # 1190 Location



Photo # 1191 Open ended pipe on production unit

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 1-31 (RL1) Pad

Location #: 323999



Photo # 1192 Open ended pipe on production unit