

Inspection Photos

Location Name: CAERUS PICEANCE LLC RULISON FEDERAL RA11 Pad

Location #: 334688



Photo # 996 From entrance to location



Photo # 997 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC RULISON FEDERAL RA11 Pad

Location #: 334688



Photo # 998 Location



Photo # 999 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC RULISON FEDERAL RA11 Pad

Location #: 334688



Photo # 1000 Location



Photo # 1001 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC RULISON FEDERAL RA11 Pad

Location #: 334688



Photo # 1002 Construction barrier/wildlife protection needs maintenance



Photo # 1003 Construction barrier/wildlife protection needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC RULISON FEDERAL RA11 Pad

Location #: 334688



Photo # 1004 Methanol tank lacks required information



Photo # 1005 Methanol tank lacks required information



Inspection Photos

Location Name: CAERUS PICEANCE LLC RULISON FEDERAL RA11 Pad

Location #: 334688



Photo # 1006 Flowline heating insulation open ended