

**Box Elder J #1
DIA Remediation Project
Photographic Log
City and County of Denver**




Photo 1: Box Elder J #1 former AST excavation area, 8/28/2023.



Photo 2: SS11 collected from the base of AST excavation area, 8/28/2023.

**Box Elder J #1
DIA Remediation Project
Photographic Log
City and County of Denver**



Photo 3: Former flowline excavation area, 8/28/2023.




Photo 4: SS12 collected from the base of the former flowline excavation area, 8/28/2023.

Box Elder J #1
DIA Remediation Project
Photographic Log
City and County of Denver



Photo 5: Former pumping unit excavation area, 8/28/2023.




Photo 6: SS13 collected from the base of the pumping unit excavation area, 8/28/2023.

Box Elder J #1
DIA Remediation Project
Photographic Log
City and County of Denver



Photo 7: SS14 collected from the south sidewall of the pumping unit excavation area, 8/28/2023.



Photo 8: SS15 collected from the north sidewall of the pumping unit excavation area, 8/28/2023.

**Box Elder J #1
DIA Remediation Project
Photographic Log
City and County of Denver**



Photo 9: SS16 collected from the west sidewall of the pumping unit excavation area, 8/28/2023.




Photo 10: SS17 collected from the east sidewall of the pumping unit excavation area, 8/28/2023.