

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/25/2023

Submitted Date:

10/02/2023

Document Number:

701007385

FIELD INSPECTION FORM

Loc ID 311526 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	
Rogers, Bob	719-767-8851	brogers@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207587	WELL	TA	09/02/1987	OW	017-06522	WHITE 22-25 3	TA

General Comment:

P&A Inspection

Location

Lease Road:

Type Access

comment: Gravel road through farm ground

Corrective Action:

Date:

Overall Good:

Signs/Marker:

Type WELLHEAD

Comment: Lease sign by wellhead

Corrective Action:

Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 207587 Type: WELL API Number: 017-06522 Status: TA Insp. Status: TA

Cement

Cement Contractor

Contractor Name: HP Oilfield Services

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 2235/1635/388

Cement Volume (sx): 275 SXS

Good Return During Job: YES

Cement Type: 60/40 POZ W/4% CaCl

Comment: HALDE WATER, CODELL WELL SERVICE, HP OILFIELD SERVICE. MIRU HP, PUMP 60 SXS THRU CICR @ 2235' W/30 SXS ON TOP. MIRU CODELL, POOH W/TBG, RIH W/CICR TO 1635'. MIRU HP, PUMP 40 SXS THRU W/15 SXS ON TOP. MIRU CODELL POOH W/TBG. MIRU HP, PUMP 10BBLS H2O, BULLHEAD 130 SXS CMT DOWN CSG W/CMT TO SFC.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT