

Inspection Photos

Loc: 309300

Operator: OGRIS OPERATING LLC

Inspection Date: 9/28/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest along the main road



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309300 | Date: 9/28/2023

Inspection Photos



Photo 2. There appears to have been sand bags placed in the erosion channel that are degraded and need to be removed and replaced with new BMP's.



Inspection Photos



Photo 3. Facing southeast along the access road toward the wellsite. There is an erosion channel along the road side that could use BMP's.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309300 | Date: 9/28/2023

Inspection Photos



Photo 4. Facing southeast toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309300 | Date: 9/28/2023

Inspection Photos



Photo 5. Facing northwest toward the wellsite. There are several hoses laying on the ground not in containment.

