

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403548285

Date Received:  
10/03/2023

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Labowskie, Steve

steve.labowskie@state.co.us

.General

sjninspections@ikavenergy.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 712700685

Inspection Date: 09/29/2023

FIR Submit Date: 09/29/2023

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

#### LOCATION - Location ID: 325931

Location Name: THACKER GAS UNIT-  
N34N7W

Number: 9SENW

County: LA PLATA

Qtrqr: SENW Sec: 9 Twp: 34N Range: 7W Meridian: N

Latitude: 37.230473 Longitude: -107.645936

#### FACILITY - API Number: 05-067-

-00

Facility ID: 215586

Facility Name: THACKER

Number: 1

Qtrqr: SENW Sec: 9 Twp: 34N Range: 7W Meridian: N

Latitude: 37.230473 Longitude: -107.645936

### CORRECTIVE ACTIONS:

1 CA# 182650

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002..(2).D.

Date: 10/07/2023

Response: CA COMPLETED

Date of Completion: 10/02/2023

Operator  
Comment:

Cleaned up contaminated soil around wellhead and pump jack skid.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: CA complete. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Grace Bryson

Signed: \_\_\_\_\_

Title: Permitting Specialist I

Date: 10/3/2023 9:44:17 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

403548296	Thacker 1, CA photos
-----------	----------------------

Total Attach: 1 Files