

Inspection Photos
Location Name: Cosslett B 1
Location ID: 317996



Photo 1 well head and equipment



Photo 2 well head and equipment

Inspection Photos
Location Name: Cosslett B 1
Location ID: 317996



Oct 3, 2023 11:51:05 AM
+40.0859N -104.9727W
156° SW
Weld County

Energy & Carbon Management Commission

Photo 3 pumping unit



Oct 3, 2023 11:51:25 AM
+40.0861N -104.9727W
335° NW
Weld County

Energy & Carbon Management Commission

Photo 4 electrical panel