

Inspection Photos

9/27/2023

Operator: EXXON MOBIL CORPORATION

#28600

Location ID: 391114

Inspection No: 696205295

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: EXXON MOBIL CORPORATION #28600

Location ID: 391114



Photo 1: Photos provide an overview of the Location. Site and slopes have been stabilized and Location returned to agriculture.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: EXXON MOBIL CORPORATION #28600

Location ID: 391114



September 27, 2023



September 27, 2023

Photo 2: Site and slopes have been stabilized and Location returned to agriculture.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources