

# Inspection Photos

9/27/2023

**Operator:** LARAMIE ENERGY LLC #10433

**Location ID:** 312503

**Inspection No:** 696205297

Mesa County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 312503



**Photo 1:** Photo 1-2 taken from the north end of the Location. Photos provide an overview of the site from east, southeast, southwest to west.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 312503



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 312503



**Photo 3:** Photos 3-4 provide examples showing Scotch thistle observed throughout the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 312503



September 27, 2023



September 27, 2023

**Photo 4:** Site and slopes have been stabilized and Location returned to agriculture.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 312503



**Photo 5:** Photos examples showing Saltcedar tamarisk observed on the Location.



## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 312503



**Photo 7:** Photo example showing Cheatgrass (green), Jointed Goatgrass (blue) and Bulbous Bluegrass (red) observed on Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources