

Inspection Photos
Location Name: John A. Kunzman 2
Location ID: 332891




Photo 1 Overgrown undesirable vegetation all around location ROW



Photo 2 WH sign

Inspection Photos
Location Name: John A. Kunzman 2
Location ID: 332891



Photo 3 Overgrown undesirable vegetation around the WH



Photo 4 Overgrown undesirable vegetation around the ancillary equip.