

Inspection Photos  
Location Name: UPRR\_VETTER\_21-31  
Location ID: 320174



Photo #1 Crude tank & P/W tank.

Photo #2 Weeds around tanks.

Inspection Photos  
Location Name: UPRR\_VETTER\_21-31  
Location ID: 320174



**Photo #3 Separator.**

**Photo #4 Weeds around separator house.**

Inspection Photos  
Location Name: UPRR\_VETTER\_21-31  
Location ID: 320174



**Photo #5 Pump jack & weeds**