

Inspection Photos
Location Name: UPRR 23 PAN AM D-3
Location ID: 319938



Photo #1 Crude tank & weeds throughout.



Photo #2 P/W vault & weeds throughout.

Inspection Photos
Location Name: UPRR 23 PAN AM D-3
Location ID: 319938



Photo #3 Separator, meter box & weeds throughout.



Photo #4 Well Head, weeds throughout.

Inspection Photos
Location Name: UPRR 23 PAN AM D-3
Location ID: 319938



Photo #5 Access road unmaintained.