

Inspection Photos
Location Name: PARMLEE-63N62W 1SWNW
Location ID: 327604



October 3, 2023 at 9:31 AM
+40.2568, -104.2757
217° SW
Weld County
Energy & Carbon Management Commission

Sign & Overgrown Vegetation



Inspection Photos
Location Name: PARMLEE-63N62W 1SWNW
Location ID: 327604



Overgrown Vegetation



Overgrown Vegetation

Inspection Photos

Location Name: PARMLEE-63N62W 1SWNW Tank Battery

Location ID: 327604



Weathered Berrms & Overgrown Vegetation



Weathered Berrms & Overgrown Vegetation

Inspection Photos

Location Name: PARMLEE-63N62W 1SWNW Tank Battery

Location ID: 327604



Overgrown Vegetation



Overgrown Vegetation



Inspection Photos

Location Name: PARMLEE-63N62W 1SWNW Tank Battery

Location ID: 327604



Overgrown Vegetation



Overgrown Vegetation

Inspection Photos

Location Name: PARMLEE-63N62W 1SWNW Tank Battery

Location ID: 327604



Overgrown Vegetation



Overgrown Vegetation