

Inspection Photos

9/29/2023

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 312736

Inspection No: 696205303

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312736



Photo 1: Photos taken from the southwest end of the Location, facing northwest and southwest. Photos show areas of the Location where gravel/road base remains on site. Desirable vegetation establishment within the graveled areas is sparse. Unable to find evidence that compaction alleviation (cross ripping to a minimum depth of 18 inches) had been performed. Additionally, photo right also shows vehicles appear to have traveled over the reclamation, resulting in degradation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312736



Photo 2: Photos taken from the central areas of the Location. Photos show gravel/road base remains on site. Desirable vegetation establishment within the graveled areas is sparse and not progressing towards 1004 standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312736



Photo 3: Photos taken from the south end of the Location, facing northwest and northeast. See comments under photo 1. Areas above the dotted line are where gravel/road base remains on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312736



Photo 4: Photo taken from the northwest end of the Location, facing east. See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312736



Photo 5: Photos taken from perimeter areas of the Location where gravel has been removed, and vegetation is progressing towards 1003 standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312736



Photo 6: Photo taken with use of a sUAS. Yellow polygon represents areas where gravel/road base remain, and where reclamation is not progressing towards 1004 standards



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312736



Photo 7: Photo taken with use of a sUAS. Yellow polygon represents areas where gravel/road base remain, and where reclamation is not progressing towards 1004 standards



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources