

Inspection Photos
Location Name: WPF III-66N64W/18NWNE
Location #: 323559



Photo #1
WPF III A18-2 Battery site
Inactive / Shut-down
Formerly served:
WPF III A 18-7, Carlson A18-17;
Plugged & Abandoned | PA



Photo #2
WPF III A18-2 Battery site
Inactive / Shut-down
Tank(s): SE corner



Inspection Photos
Location Name: WPF III-66N64W/18NWNE
Location #: 323559



Photo #3
WPF III A18-2 Battery site
Inactive / Shut-down
Separator(s), ECD(s)



Photo #4
WPF III A18-2 Battery site
Inactive / Shut-down
Battery sign



Inspection Photos
Location Name: WPF III-66N64W/18NWN
Location #: 323559



Photo #5
WPF III A18-2 (123-13195) Wellsite
Temporarily Abandoned | TA
prior photo

