

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN RMV 84-34 Pad

Location ID: 323986



Oct 4, 2023 at 10:33:52 AM



Oct 4, 2023 at 10:34:17 AM

Photo # 1415 From entrance to location

Photo # 1416 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN RMV 84-34 Pad

Location ID: 323986



Photo # 1417 Location



Photo # 1418 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN RMV 84-34 Pad

Location ID: 323986



Photo # 1419 Location



Photo # 1420 Netting/wildlife protection needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN RMV 84-34 Pad

Location ID: 323986



Photo # 1421 Netting/wildlife protection needs maintenance



Photo # 1422 Open ended pipe/wildlife hazard



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC JUHAN RMV 84-34 Pad

Location ID: 323986



Photo # 1423 Stained soils & gravel