

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/05/2023

Submitted Date:

10/05/2023

Document Number:

701007480

FIELD INSPECTION FORM

Loc ID 303342 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 25255
Name of Operator: DUKE GAS COMPANY LLC
Address: 22500 COUNTY RD 24
City: VERNON State: CO Zip: 80755

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Cantrall, Diana		djcantrall@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252933	WELL	PR	11/01/2020	GW	125-06809	BRUEGGMAN 23-1	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to wellhead		
Corrective Action:			Date:
Type	OTHER		
Comment:	Lease sign mounted to meter shed		
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	Meter run is 250' west of wellhead		
Corrective Action:			Date:
Type: Horizontal Separator	# 1		
Comment:	HGS on north side of meter shed		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator 50% buried on north side of meter shed		
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 252933 Type: WELL API Number: 125-06809 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Meter run is 250' west of wellhead](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: Wellhead is in farm ground and location is farmed over

Corrective Action: Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: _____ Lat: 39.955460 Long: -102.392380

Reference Point: SE Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action Date: _____