

# Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH 128 Pad

Location # 335132




Photo # 1769 From entrance to location

Photo # 1770 Location

# Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH 128 Pad

Location # 335132



Photo # 1771 Location



Photo # 1772 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH 128 Pad

Location # 335132



**Photo # 1773 Location**



**Photo # 1774 Location**

## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH 128 Pad

Location # 335132



Photo # 1775 Open ended pipe/wildlife hazard



Photo # 1776 Open ended pipe/wildlife hazard

## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH 128 Pad

Location # 335132



**Photo # 1777 Production tank lacks required information**

**Photo # 1778 Production tank lacks required information**