

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SESE

Location ID: 335250

Date: 10/4/2023



Entrance to Location – Photo #06778



Wellheads – Photo #06780

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SESE

Location ID: 335250

Date: 10/4/2023



Oct 4, 2023 at 10:25:05
3555 CR-215
Parachute CO 81635
United States



Oct 4, 2023 at 10:25:40
3555 CR-215
Parachute CO 81635
United States

Separators – Photo #06768

Tank Battery – Photo #06771

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SESE

Location ID: 335250

Date: 10/4/2023



**Lack of Stabilization/Insufficient Vehicle Tracking BMPs at
Location Entrance/Exit – Photo #06784**