

Operator: 8 North

Location Name: DF RANCH PC GK02-77HN

Loc ID: 428119

Inspection: 696305279



Exhibit A

CA: 300 BBL Water Tank - NFPA Label; see photos. Install sign to comply with Rule 605.h.

CA Resolution: A new label has been installed to comply with Rule 605.h.



Exhibit A

CA: Unused Equipment at Compressor Site - Black Chemical Stand, Red Chemical Drums, Chemical Stand, Black Chemical Drum and Load line Bucket. See Photos. Comply with Rule 606.

CA Resolution: Operator has properly addressed and cleared identified equipment and materials to comply with Rule 606.

CA: Trash and Debris including Tumbleweeds inside Compressor Building, unused Netting, Metal Siding, and Brown Tarp. Comply with Rule 606.

CA Resolution: Operator has properly addressed and cleared identified trash and debris to comply with Rule 606.