

Operator: 8 North

Location Name: DF RANCH 1161-9-32

Loc ID: 414980

Inspection: 696305302



Exhibit A



Exhibit B

CA: Livestock panels- Fencing in disrepair; see photos. Comply with rule 606

CA Resolution: Operator has addressed identified issues and appropriately installed fencing and panels to comply with Rule 606.