

Inspection Photos

Loc: 379485

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 10/5/2023

County: Bent



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south along the access road. The two track road remains but vegetation appears to have mostly re-established along the former access road.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:379485 | Date: 10/5/2023

Inspection Photos



Photo 2. Facing south toward the location. The location consists primarily of undesirable weeds (*Kochia* sp.) and bare soil. The location has not reestablished a uniform vegetation cover of 80% of reference area levels.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:379485 | Date: 10/5/2023

Inspection Photos



Photo 3. Facing southwest toward the location. The location consists primarily of undesirable weeds (*Kochia* sp.) and bare soil. The location has not reestablished a uniform vegetation cover of 80% of reference area levels.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:379485 | Date: 10/5/2023

Inspection Photos



Photo 4. West side of the location facing east. The location consists primarily of undesirable weeds (*Kochia* sp.) and bare soil. The location has not reestablished a uniform vegetation cover of 80% of reference area levels.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:379485 | Date: 10/5/2023

Inspection Photos



Photo 5. View of groundcover shows undesirable weeds which are found throughout the location. (Kochia sp)



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:379485 | Date: 10/5/2023

Inspection Photos



Photo 6. Facing northeast toward the surrounding undisturbed reference areas which consists of Blue grama, Sand dropseed, Buffalo grass among other native species.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:379485 | Date: 10/5/2023

Inspection Photos



Photo 7. Drone aerial photo (taken 8/9/23) facing west down toward the location. There are areas bare vegetation which appear to be impacted from the wellsite operations.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:379485 | Date: 10/5/2023

Inspection Photos



Photo 8. Drone aerial photo (taken 8/9/23) facing north down toward the location. The inspectors truck is shown in the upper left for scale.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:379485 | Date: 10/5/2023

Inspection Photos



Photo 9. Drone aerial photo (taken 8/9/23) facing east down toward the location. There are areas bare vegetation which appear to be impacted from the wellsite operations.



Inspection Photos



Photo 10. Drone aerial photo (taken 8/9/23) facing southeast toward the surrounding undisturbed reference area which has a uniform perennial vegetation cover.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:379485 | Date: 10/5/2023