

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2023

Submitted Date:

10/10/2023

Document Number:

713600292**FIELD INSPECTION FORM**Loc ID 379485 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #225City: AURORA State: CO Zip: 80016**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ingve, Edward	303-680-4725	ed@renegadeoilandgas.com	
Freese, Steve		steve.freese@state.co.us	
Sanchez, Chris		chris.sanchez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206272	WELL	PA	08/10/2018	GW	011-06018	STATE 918-S 1	RI

**General Comment:**

On 10/5/2023, Ryan Costa conducted a follow up of the previous reclamation inspection #713600082.  
The corrective action of the previous reclamation inspection has not been performed.  
Operator is directed to perform corrective actions outlined on this inspection report immediately.

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment:

The location appears to have impacted soils preventing desirable vegetaion establishment.  
The soil impacts will need to be investigated and sampled to delineate the vertical and horizontal extent.

Corrective Action:

Submit Form 19 to report historic spill of impacted material and Contact ECMC EPS staff per Rule 912.b.

Date: 10/05/2023

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat

Long

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed **Fail** \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% **Fail** \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present **Fail** \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:

The location has not established a desirable uniform vegetation cover of at least 80% of reference area levels. There were two 100 ft. transects conducted at the location which showed only bare soils and undesirable weeds. It appears there are impacted soils preventing desirable vegetation establishment. The soil impacts will need to be investigated and sampled to delineate the vertical and horizontal extent. Operator will need to submit a form 27 to investigate and sample soils per Rule 913. Contact EPS staff for directives. Corrective action will remain out of compliance until completed.

Corrective Action: **Comply with 1004 Rules.**

Date **08/09/2023**

Overall Final Reclamation

**Fail**

Well Release on Active Location ☐

Multi-Well Location ☐

#### COGCC Comments

Comment	User	Date
Operator will need to adhere to the concentrations for soil cleanup in Table 915-1. Agronomic soil analysis should include at a minimum: - pH, electrical conductivity (EC), SAR, and Boron (methods per the Table 915-1; all values rounded to the nearest 0.10); - organic matter (Walkely-Black method); - nitrate, ammonium nitrogen, phosphorus, potassium, zinc, iron, manganese, copper, and chloride (all using AD-DTPA extraction); - lime and texture estimates; - percent calcium carbonate equivalency (gravimetric); - texture (hydrometer with textures reported as USDA); and - plant available Selenium <sup>1</sup>	CostaR	10/10/2023
Soil sampling and Analysis will need to be conducted per Rule 915.e. Review 915.e.(2) - Soil Sampling and Analysis Guidance document for more details.	CostaR	10/10/2023

#### Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
713600293	Inspection Photos	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6280464">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6280464</a>