

Inspection Photos

Location Name: CAERUS PICEANCE LLC, NOLTE-67S96W/14NESE

Location ID: 324087

Date: 10/10/2023



SW Corner of Location – Photo #06862



Wellhead – Photo #06863

Inspection Photos

Location Name: CAERUS PICEANCE LLC, NOLTE-67S96W/14NESE

Location ID: 324087

Date: 10/10/2023



Separator – Photo #06866



Tank Battery – Photo #06865